

## pH PenTESTER, pHep® 4 & 5®



- Dual display shows pH & Temp. in °C or F°
- 1 or 2 point calibration with auto recognition of both standard and NIST buffer sets
- Stability indicator / hold feature prompts user when to take reading; display freezes for easy/accurate recording
- Stainless steel probe for fast, precise temperature measurement
- Replaceable pH electrode with an extendable junction
- Automatic temperature compensation
- Battery level check for proper measurements
- Waterproof casing floats
- WARRANTY: 1 YR on tester, 6 MONTH on Electrode
- Dims./Wgt.: 163 x 40 x 26 mm / 100g

*Supplied complete with protective cap, electrode removal tool, batteries (300 hrs) and instructions.*

		M104426	M104427
Range	pH:	-2.0 to 16.0	-2.0 to 16.0
	Temp.:	-5.0° to 60°C / 23° to 140°F	
Resol.:	pH	0.1	0.01
	Temp.:	0.1°C / 0.1°F	
Accuracy:	pH	±0.1	±0.05
	Temp.:	±0.5°C (±1°F)	
Environment:		-5 to 50°C (23° to 122°F); RH max 100%	



www.LABMART.com • 800-684-1234 • 908-561-1234 • Fax: 908-561-3002